


A New, Patented Bunion Treatment



Bunions: More than a Bump

A common misconception is that a bunion is simply an overgrowth of bone that can be "shaved off"...

In reality, bunions are complex deformities caused by an unstable joint in the middle of the foot which allows the metatarsal bone to drift out of alignment.



Fix the Root of the Problem and
Walk within Days of Surgery¹ with

Lapiplasty[®]

3D Bunion Correction[™]

Normal Foot



Did You Know?

87%





of bunions
are misaligned
in THREE dimensions
(i.e. 3D deformity)²

Traditional Surgery: 2D solution for 3D problem

In a 2D osteotomy, the metatarsal bone is cut in half and pushed over. This addresses the cosmetic bump, but not the root cause. It's like putting a band aid on the problem.

Fix it Right the First Time™ Lapiplasty® 3D Bunion Correction™

- ✓ Fix the root cause of the bunion
- ✓ Address all 3 dimensions
- ✓ Walk within days of surgery
– no casts!*



1 in 3

Did You Know?
Patients are **dissatisfied** (aesthetics, pain, & function) after traditional 2D bunion surgery.³

*See FAQ's.